

# CNC PROGRAMMING WORKBOOK

| CODE       | FUNCTION  |
|------------|---|
| <b>G00</b> | Rapid traverse motion; This is used for non-cutting rapid moves of the machine axis, or rapid retract moves after cuts have been completed.<br>Maximum rapid motion (I.P.M.) of a CNC Machine will vary dependent on machine model. |
| <b>G01</b> | Linear interpolation motion; Used for cutting in a straight line under a controlled feedrate. Maximum feed rate (I.P.M.) of a CNC Machine will vary depending on the model of the machine.  |
| <b>G02</b> | Circular Interpolation, Clockwise   |
| <b>G03</b> | Circular Interpolation, Counterclockwise  |
| <b>G04</b> | Dwell   |
| <b>G17</b> | Circular Motion XY Plane Selection  |
| <b>G20</b> | Verify Inch Coordinate Positions  |
| <b>G21</b> | Verify Metric Coordinate Positions  |
| <b>G28</b> | Machine Home (Rapid traverse) G91 is required for rapid move to the G28 reference point.  |
| <b>G40</b> | Cutter Compensation CANCEL  |

## MILL-LESSON-2

### INTRODUCTION TO CNC CODES

**LESSON-2 - INTRODUCTION TO CNC CODES**  
**AUTOMATIC TOOL CHANGER**  
**STANDARD TOOL CAROUSEL**

*The CNC Machining Center used in this text is set-up with following tools. All program examples and exercises in this workbook are using the tools and tool numbers listed below.*

| <b>Carousel #</b> | <b>Tool Description</b>                       |
|-------------------|---|
| <b>1</b>          | <b>0.125" Diameter Flat End Mill</b>          |
| <b>2</b>          | <b>0.250" Diameter Flat End Mill</b>          |
| <b>3</b>          | <b>0.375" Diameter Flat End Mill</b>          |
| <b>4</b>          | <b>0.500" Diameter Flat End Mill</b>          |
| <b>5</b>          | <b>0.750" Diameter Flat End Mill</b>          |
| <b>6</b>          | <b>0.375" Diameter Spot Drill</b>             |
| <b>7</b>          | <b>0.250" Diameter Drill</b>                  |
| <b>8</b>          | <b>0.201" Diameter Drill – Number 7 drill</b> |
| <b>9</b>          | <b>0.25"-20 UNC Tap</b>                       |
| <b>10</b>         | <b>#4 Center Drill</b>                        |

## COMMONLY USED PREPARATORY G CODES

| CODE       | FUNCTION  |
|------------|---|
| <b>G00</b> | Rapid traverse motion; This is used for non-cutting rapid moves of the machine axis, or rapid retract moves after cuts have been completed.<br>Maximum rapid motion (I.P.M.) of a CNC Machine will vary dependent on machine model. |
| <b>G01</b> | Linear interpolation motion; Used for cutting in a straight line under a controlled feedrate. Maximum feed rate (I.P.M.) of a CNC Machine will vary depending on the model of the machine.  |
| <b>G02</b> | Circular Interpolation, Clockwise   |
| <b>G03</b> | Circular Interpolation, Counterclockwise  |
| <b>G04</b> | Dwell   |
| <b>G17</b> | Circular Motion XY Plane Selection  |
| <b>G20</b> | Verify Inch Coordinate Positions  |
| <b>G21</b> | Verify Metric Coordinate Positions  |
| <b>G28</b> | Machine Home (Rapid traverse) G91 is required for rapid move to the G28 reference point.  |
| <b>G40</b> | Cutter Compensation CANCEL  |
| <b>G41</b> | Cutter Compensation LEFT of the programmed path   |
| <b>G42</b> | Cutter Compensation RIGHT of the programmed path  |
| <b>G43</b> | Tool Length Compensation  |
| <b>G49</b> | Tool Length Compensation CANCEL   |
| <b>G53</b> | Positions the machine axis relative to Machine Home. It is non modal.   |
| <b>G54</b> | Work Coordinate #1 (Part zero offset location)  |
| <b>G80</b> | Canned Cycle CANCEL   |
| <b>G81</b> | Drill Canned Cycle  |
| <b>G82</b> | Spot Drill Canned Cycle   |
| <b>G83</b> | Peck Drill Canned Cycle   |
| <b>G84</b> | Tapping Canned Cycle  |
| <b>G90</b> | Absolute Programming Positioning  |
| <b>G91</b> | Incremental Programming Positioning   |
| <b>G98</b> | Canned Cycle Initial Point Return   |
| <b>G99</b> | Canned Cycle Rapid (R) Plane Return   |

## COMMONLY USED MISCELLANEOUS M CODES

| CODE       | FUNCTION   |
|------------|--|
| <b>M00</b> | <p>The M00 code is used for a Program Stop. The spindle stops and the coolant is turned off.<br/>Pressing CYCLE START again will continue the program.</p>   |
| <b>M01</b> | <p>The M01 code is used for an Optional Program Stop command.<br/>Pressing the OPT STOP key on the control panel signals the machine to perform a stop command when the control reads an M01 command. It will then perform like an M00. Optional stops are useful when machining the first part to allow for inspection of the part as it is machined.</p> |
| <b>M03</b> | <p>Starts the spindle CLOCKWISE used for most machining. Must have a spindle speed defined.<br/>The M03 is used to turn the spindle on at the beginning of program or after a tool change.</p>   |
| <b>M04</b> | <p>Starts the spindle COUNTERCLOCKWISE. Must have a spindle speed defined.</p>   |
| <b>M05</b> | <p>STOPS the spindle.<br/>The M05 is used to turn the spindle off at the end of program or before a tool change. If the coolant is on, the M05 will turn it off.</p>   |
| <b>M06</b> | <p>The tool change command along with a tool number will action a tool change. This command will automatically stop the spindle, Z-axis will move up to the machine zero position and the selected tool will be put in the spindle. The coolant pump will turn off right before executing the tool change.</p>   |
| <b>M08</b> | <p>Coolant ON command.</p>   |
| <b>M09</b> | <p>Coolant OFF command.</p>  |
| <b>M30</b> | <p>Program End and Reset to the beginning of program.</p>  |

Note: Only one "M" code can be used per line. And the M-codes will be the last command to be executed in a line, regardless of where it is located in that line.

## EXAMPLE OF PROGRAM START-UP BLOCKS

|  |   |   |
|--|---|---|
| <b>%</b>                                   | Programs must begin and end with “%” depending on the type of control.  |   |
| <b>O00023</b>                              | Letter “O” and up to a five digit program number.<br>Blocks are always terminated by the “;” symbol:<br>End of Block (EOB)  |   |
| <b>N10 G20</b>                             | Nnn - Sequence Number<br>G20 - Verify Inch  | Startup<br>Block<br>(Machine<br>Default<br>Setting) |
| <b>N20 G00 G17 G40 G49 G80 G90</b>         | G00 - Rapid Traverse<br>G17 - X, Y Circular Plane Selection<br>G40 - Cutter Compensation Cancel<br>G49 - Tool Length Compensation Cancel<br>G80 - Canned Cycle Cancel<br>G90 - Absolute Programming   |   |
| <b>N30 T8 M06</b>                          | T8 - Tool number #8 to be loaded into the spindle.<br>M06 - Tool Change   |   |
| <b>N40 G00 G90 G54 X1.0 Y1.0 S4000 M03</b> | G00 - Rapid Traverse<br>G90 - Activates control to be in ABSOLUTE.<br>G54 - Selects work coordinate offset system No. 1<br>X__ - Axis move to initial X position.<br>Y__ - Axis move to initial Y position.<br>S4000 - Spindle speed 4000 RPM for this tool.<br>M03 - Turns the spindle on in a clockwise direction   |   |
| <b>N50 G43 H8 Z2.0</b>                     | G43 - Tool Length Compensation: Recognizes the tool length offset value stored in the Hnn code offset display register in the offset length display.<br>H8 - Defines to the control the offset register the tool offset value is stored in.<br><b>* Tool Length offset # = Tool #</b><br>Z2.0 - Informs the control to move from full spindle retract to this Z value and apply the tool length offset. |   |

## EXAMPLE OF PROGRAM END BLOCKS

|  |   |   |
|--|---|---|
| <b>N200 G00 Z2.0</b>                                 | G00 - Rapid Traverse<br>Z2.0 – Retracts tool to 2.0 above part zero   |   |
| <b>N210 M05</b>                                      | M05 – Turn off spindle  |   |
| <b>N220 G28 G91 Z0</b><br><br><i>* N220 G53 Z0</i>   | G91 - Incremental Programming<br>G28 - Machine Zero Return<br>Z0 - Z axis in the up direction to machine zero | <b><i>Send to machine zero Z-axis first to avoid any crash.</i></b> |
| <b>N230 G28 X0 Y0</b><br><br><i>* N230 G53 X0 Y0</i> | G28 - Machine Zero Return<br>X0 - X axis to machine zero<br>Y0 - Y axis to machine zero                       | <b><i>*G53 is another way to return to machine zero</i></b>         |
| <b>N240 M30</b>                                      | M30 – End of Program and Reset  |   |

## EXAMPLE OF PROGRAM TOOL CHANGE LINES

|   |   |   |
|---|---|---|
| <b>N100 G00 Z2.0</b>                        | Rapid Traverse and Retracts tool to 2.0 above part zero |   |
| <b>N110 M05</b>                             | M05 – Turn off spindle                                  |   |
| <b>N120 G28 G91 Z0 ; / *N120 G53 Z0</b>     | Machine Zero Return - Z axis                            | <b><i>Send to machine zero Z-axis first to avoid any crash.</i></b> |
| <b>N130 G28 X0 Y0 / *N130 G53 X0 Y0</b>     | Machine Zero Return - X, Y axis                         |   |
| <b>N140 M01</b>                             | Optional Program Stop                                   |   |
| <b>N150 T9 M06</b>                          | Tool Change - Tool # 9                                  |   |
| <b>N160 G00 G90 G54 X1.0 Y1.0 S4000 M03</b> | Turn on the spindle and Rapid traverse to X1. Y1.       |   |
| <b>N170 G43 H9 Z2.0</b>                     | Tool Length compensation for Tool #9 (H9)               |   |

\*G53 - Positions the machine axis relative to Machine Home. It is non modal.

## RAPID G00 AND LINEAR G01 INTERPOLATION

### G00 RAPID TRAVERSE

This code is used for rapid motion of the cutter in air to traverse from one position to another as fast as possible. This code will work for all axis motion up to three axes at once.

This G00 code is modal and causes all the following blocks to be in rapid motion until another Group 01 code is specified. The actual rapid federate is dependent on the machine.

Generally, rapid motions "will not" be in a straight line. All the axes specified are moved at the maximum speed and will not necessarily complete each axis move at the same time. It activates each axis drive motor independently of each other and, as a result, the axis with the shortest move will reach its destination first. So ***you need to be careful of any obstructions to avoid with this type of rapid move.***

- G00 is used when you are positioning the cutter in 'fresh air'.
- Retracting from a hole you have drilled.
- Rapid traverse is not used when cutting the part.
- Used incorrectly, rapid traverse will break a cutter very easily.

### G01 LINEAR INTERPOLATION

This G code provides for straight line (linear) motion with programmed feedrate for all axis motions from point to point. Motion can occur up to three axes at once.


All axes specified will start at the same time and proceed to their destination and arrive simultaneously at the specified feedrate.

To program a feedrate, the F command is used. The F command is modal and may be specified in a previous block.

G01 is used for

- Drilling a hole
- Machining a slot
- Machining a profile



# LESSON-2 - CNC - PART #1





## LESSON-2 - CNC - PART #1

- **WORK OUT THE X AND Y COORDIANTES FOR HOLES 1,2 AND 3**
  - XOYO is at the centre of the part




| G90      | X | Y |
|----------|---|---|
| <b>1</b> |   |   |
| <b>2</b> |   |   |
| <b>3</b> |   |   |

## LESSON-2 - CNC - PART #1

▪ ***PROGRAM TO SPOT DRILL THE THREE HOLES ONLY USING A COMBINATION OF G00 AND G01 (CANNED CYCLE DRILL WILL BE USED LATER)***

- Below is the program to spot drill the three holes with an explanation of each block
- Use a 0.375" diameter Spot Drill Tool # 6
- Spindle Speed = 2750 Feed rate = 11 IPM
- Spot Drill Depth = Z-0.150"
- X0Y0 is at the centre of the part.
- Z=0 is the top of the part.
- Information inside the parenthesis ( ) is a comment.
- The CNC control will ignore all text between the parenthesis



|   |   |
|---|---|
| %                                       | (Program must begin and end with a %)   |
| O1                                      | ( Program #1 - CNC-PART-1-SPOT DRILLING ONLY )  |
| N10 G20                                 | (Inch programming)  |
| N20 G00 G17 G40 G49 G80 G90             | (MACHINE DEFAULT SETTING)   |
| N30 T06 M06                             | (T6-Select tool number 6 to be loaded M06-Activates the tool changer)                       |
| N40 G00 G90 G54 X-1.0 Y-0.875 S2750 M03 | – (Rapid to the X and Y position and turn on the spindle at 2750 RPM)                       |
| N50 G43 H06 Z0.1                        | (G43 - Activate the tool offset value stored in H06 and rapid to Z0.1)                      |
| N60 G01 Z-0.15 F11.0                    | (Hole #1 - Feed down to Z depth at 11 inches per minute)                                    |
| N70 G00 Z0.1                            | (G00- Retract out of hole #1 at rapid to 0.1 above the top of the work piece)               |
| N80 X0 Y0                               | (G00 is modal - Move at rapid in the X and Y axis to hole #2)                               |
| N90 G01 Z-0.15                          | (Hole #2 - Feed down to Z depth at 11 inches per minute, Feed rate is modal)                |
| N100 G00 Z0.1                           | (G00- Retract out of hole #2 at rapid to 0.1 above the top of the work piece)               |
| N110 X1.0 Y0.875                        | (G00 is modal - Move at rapid in the X and Y axis to hole #3)                               |
| N120 G01 Z-0.15                         | (Hole #3 - Feed down to Z depth at 11 inches per minute, Feed rate is modal)                |
| N130 G53 G00 Z0 M05                     | (G53 – Machine Zero positioning, non modal. Rapid to machine zero in Z, switch spindle off) |
| N140 G53 X-15.0 Y0                      | (G53 – Rapid in relation to machine zero X-15.0 and Y0)                                     |
| N150 M30                                | (Program end rewind program to the beginning)   |
| %                                       | (Program must begin and end with a %)   |

