



# MILL-LESSON-9 SURFACE HIGH SPEED - OPTIAREA SURFACE HIGH SPEED - HYBRID

camInstructor

# Objectives

You will create the geometry for Mill-Lesson-9, and then generate the toolpaths to machine the part on a CNC vertical milling machine. This Lesson covers the following topics:

### **Create a 3-dimensional drawing by:**

Creating lines. Creating arcs. Trimming geometry using Divide / Delete. Creating a revolved surface.

### Setablish Stock Setup settings:

Stock size using Bounding Box. Material for the part. Feed calculation.



### • Generate a 3-dimensional milling toolpath consisting of:

Surface High Speed - OptiArea Surface High Speed - Hybrid

# Inspect the toolpath using Mastercam's Verify and Backplot by:

Launching the Verify function to machine the part on the screen. Generating the NC- code.

### High Speed Toolpaths - HST

3D HST Hybrid toolpaths include a new Optimize cut order checkbox which defines the cut order Mastercam applies to different cutting passes in the toolpath. When selected, Mastercam works in tiers, ordering the toolpath's cutting passes based on proximity and safety. Mastercam machines features by area until it reaches a common Z-level, then repeats the process until it reaches the next common ground. The tool stays in a common ground, which reduces unnecessary motion and shortens the length of the toolpath.

Hybrid toolpaths now offer additional options for handling open and closed contours. Closed contours contain continuous motion without a need for a retract or reversal of direction. You can select climb or conventional machining for these contours. Open contours offer One Way or Zigzag cutting options. Open contours set to One Way will use the cutting method selected for closed contours.

The new Automatic Offset method controls how Mastercam handles the boundaries between steep and shallow areas. If the toolpath engages part surfaces that include core and cavity properties, Mastercam applies upper to lower offset methods to core features and lower to upper offset methods to cavity shapes.

The 3D HST toolpaths now calculate more efficient high speed motion at your part's boundaries. To improve regeneration speed, they now only recalculate the necessary sections of the toolpath instead of processing the entire toolpath when changes are made.

The 3D HST Project toolpath projects either geometry or a toolpath from an earlier operation onto surfaces. Previously, the Project toolpath was only available as a surface roughing toolpath. In Mastercam the full suite of high speed toolpath parameters are available to refine the tool motion.



# **TOOL LIST**

- 0.500 diameter bull end mill with a 0.125 corner radius to rough machine the pocket.
- 0.500 diameter ball end mill to finish machine the pocket.

# MILL-LESSON-9 - THE PROCESS

# **Geometry Creation**

- **TASK 1:** Setting environment
- **TASK 2:** Create geometry
- **TASK 3:** Trim the geometry
- TASK 4: Create the revolved surface
- **TASK 5:** Create boundary curves
- **TASK 6:** Save the drawing

# **Toolpath Creation**

- **TASK 7:** Define the rough stock using stock setup
- TASK 8: Rough the pocket using Surface High Speed OptiArea
- **TASK 9:** Finish the pocket using Surface High Speed Hybrid
- TASK 10: Verify the toolpath
- TASK 11: Save the updated Mastercam file
- TASK 12: Post and create the CNC code file



# TASK 1: SETTING THE ENVIRONMENT

Before starting the geometry creation you should set up the grid, toolbars and machine type as outlined in the **Setting the environment** section at the beginning of this text:

- 1. Set up the Grid. This will help identify the location of the origin.
- 2. Load the Workspace SETTINGS>Load Workspace>3D Toolpaths to machine a 3D part.
- 3. Set the machine type to a Haas Vertical Spindle CNC machine.

# TASK 2: CREATE GEOMETRY - X0 Y0 LOWER LEFT CORNER

In this task you will create the geometry that will be used to create the revolved surface. First you will create the circles, C1 through C4 and then create the lines 1 through 7. The arc C5 will be created using Fillet.



- Create Circle #1
- 1. Select CREATE>Arc>Circle Center point...
- 2. The Circle Center Point ribbon bar appears and you are prompted to Enter the center point.



 Before moving on, click in the space for radius and enter a value of 0.25. Next click on the icon for radius on the ribbon bar as shown below. This locks in the radius for the circles. To unlock click on the icon for diameter.



- 4. To satisfy this first prompt click on the FastPoint Icon on the Auto Cursor ribbon bar
- 5. In the space input the X (0.25) and Y (0.5) values for the center of the circle and hit enter. Note that you can use a variety of formats to enter coordinates here. This is very helpful when cutting and pasting coordinate values from another document. You do not need to input the Z value for this example.
- 6. On the ribbon bar click on **Apply** to fix the entity.

### Create Circle #2

- 7. To satisfy the prompt **Enter the center point** click on the **FastPoint** Icon on the Auto Cursor ribbon bar.
- 8. In the space input the X (0.625) and Y (0.5) values for the center of the circle and then hit the enter key.
- 9. On the ribbon bar click on **Apply (C)** to fix the entity.

### Create Circle #3

- 10. To satisfy the prompt **Enter the center point** click on the **FastPoint** Icon on the Auto Cursor ribbon bar.
- 11. In the space input the X (3.750-1.858) and Y (0.5+0.25) values for the center of the circle and then hit the enter key.

12. On the ribbon bar click on **Apply 12** to fix the entity.

### Create Circle #4

- 13. To satisfy the prompt **Enter the center point** click on the **FastPoint** Icon on the Auto Cursor ribbon bar.
- 14. In the space input the X (3.750-0.25) and Y (0.625) values for the center of the circle and then hit the enter key.
- 15. Click on the OK icon is to complete this feature.

### 16. Now select the Fit to screen icon

### Create Line #1

- 17. Select from the pull down menu: CREATE>Line>Line Endpoint...
- 18. On the graphics screen you are prompted: **Specify the first endpoint** and the Line ribbon bar appears. **Note** that the **Tangent** function is activated.

X -2.17781	<ul> <li>Υ 1.76812</li> <li>Ζ 0.0</li> </ul>	 🗞 🕥 🔿 🛝 😫 🔨 🔽 🚫 🥥
► <b>+1 +2</b>	🕅 🖬 💀 Վ 🔝 🚥	

19. To satisfy the prompt Specify the first endpoint move the cursor over to the center of the

**grid** and as you get close to the **Origin** (X0Y0) a visual cue appears. This is the cue that will allow you to snap to the origin, with this visual cue highlighted **pick the origin**.

20. To satisfy the prompt **Specify the second endpoint** move the cursor over the area of the circle shown below. Ensure there is **no visual snap cue** being displayed and click on this point. As **Tangent** is activated on the line ribbon bar the line will snap to the closest tangency point on the circle as shown below right:



21. On the ribbon bar click on Apply 😳 to fix the entity.

### Create Line #2

22. To satisfy the prompt **Specify the first endpoint** move the cursor over the area of the circle shown below. Ensure there is **no visual cue** being displayed and click on this point. As **Tangent** is activated on the line ribbon bar the line will snap to the closes tangency point on the circle.



23. To satisfy the prompt Specify the second endpoint move the cursor over the area of the circle shown below. Ensure there is no visual cue being displayed and click on this point. As Tangent is activated on the line ribbon bar the line will snap to the closest tangency point on the circle as shown below right.



24. On the ribbon bar click on Apply 🖸 to fix the entity.

### Create Line #3

25. To satisfy the prompt **Specify the first endpoint** move the cursor over the area of the circle shown below. Ensure there is **no visual cue** being displayed and click on this point.



26. To satisfy the prompt **Specify the second endpoint** move the cursor over the area of the circle shown below. Ensure there is no visual cue being displayed and click on this point. As **Tangent** is activated on the line ribbon bar the line will snap to the closest tangency point on the circle.



27. On the ribbon bar click on **Apply** to fix the entity.

### Create Line #4

28. Click in the space for Length and enter a value of 0.5 and then hit the tab key. In the space for Angle and enter a value of -40.0 and hit enter.



29. To satisfy the prompt Specify the first endpoint move the cursor over the area of the circle shown below. Ensure there is no visual cue being displayed and click on this point.



30. To satisfy the prompt **Select a line** pick the lower line as shown below:



### Create Line #5

32. To satisfy the prompt **Specify the first endpoint** use the **AutoCursor ribbon bar Override drop down list – located at top of screen on left**. Open the drop down and select **Quadrant**. Move the cursor over the area of the circle shown below right and click on the circle:



33. To satisfy the prompt Specify the second endpoint move the cursor over to the left of the

circle shown below. Ensure the visual cue for **Horizontal/Vertical** is displayed and click on this point.



space for Angle enter a value of 0 and hit enter.



### Create Line #7

38. To satisfy the prompt Specify the second endpoint move the cursor over to the right of the

circle shown below. When the visual cue for Endpoint is displayed click on this point.



39. Click on the OK icon is to complete this feature.

### Create Fillet #5

- 40. Select CREATE>Fillet>Fillet Entities...
- 41. On the Fillet ribbon bar enter .25 for the radius. Ensure the Style of radius is set to Normal and the trim button is depressed to turn the trim on.



42. When prompted to Fillet: Select an entity, select the two lines shown below:



43. Click on the OK icon to complete this feature.

# **TASK 3:** TRIM GEOMETRY

- In this task you will trim the geometry using Divide / Delete. There are many different ways to accomplish this trimming operation, this is just one method. If you make a mistake using Divide / Delete use the Undo button to start over.
- Trim the circles

**8** 

- 1. Select EDIT>Trim/Break>Trim/Break/Extend
- 2. The Trim / Extend / Break ribbon bar appears and you are prompted to Select the entity to trim/extend.

**-**

M 🛉

3. Click on the **Divide / Delete** icon to activate it as shown above. Ensure the icon is pressed down to signal that it is activated.

2 01

4. The prompt changes to **Select the curve to divide / delete.** Move the cursor over the various circles and select in order and position as shown below. The arc is trimmed back to the two closest intersections/end points as shown below. Placing the cursor over the entity to divide / delete shows a preview as shown below left.



Note: On some of the circles you will need to select them more than once to completely trim them.

5. Click on the OK icon **v** to complete this feature. The completed geometry is shown below:



# TASK 4: CREATE THE REVOLVED SURFACE

In this task you will create a revolved surface using the geometry you have just created and revolve the geometry 180 degrees about the X axis.

**Revolved surfaces** are circular in one direction. You will be prompted to chain an entity that the revolved surface will use as a profile. You may choose multiple entities to create many revolved surfaces at a time.

You are then prompted to choose a line to use as the axis of rotation and the revolved surface is created.

If you have chosen multiple entities, a surface for each entity will be created, each having a different profile and position and all using the same axis of rotation. Click Apply or Enter when done.

### Create Revolved Surface

- 1. Select from the pull down menu: CREATE>Surface>Revolved...
- 2. On the graphics screen you are prompted: **Select profile curve(s) 1.** In the **Chaining** dialog window select **Partial Chain** as shown below:
- 3. Select **line 1** and ensure the arrow is pointing upwards. If not click on the reverse icon.
- 4. Then select line 2 as shown below:



- 5. Click on the OK icon in the Chaining dialog window.
- 6. Change the End angle to 180 as shown below and hit enter:



- 7. Change the graphics view to **Isometric**
- 8. For the prompt on the screen **Select axis of rotation**, select the line shown in the diagram above in step 4.
- 9. Select the Fit to screen icon
- 10. The arrow should be pointing **downwards** and the newly created surface should look like the diagram below: If the arrow is not pointing downwards or the surface does not look like the image below, select the **Reverse** icon on the Revolved surface ribbon bar.



- 11. Click on the OK icon is set to complete this feature. The picture above is set to Wireframe display.
- 12. Select the Shaded icon to display the part in shaded mode.



- 13. Select the Wireframe icon
- to return to wireframe display.
- 14. Delete the axis of rotation as this will not be required anymore. Select the Delete entities

icon *solution* and when prompted to **Select entities** pick the line shown below and then hit enter.





# TASK 5: CREATE BOUNDARY CURVES

- When you machine the Revolved surface you will be prompted to chain an entity that the revolved surface will use as a profile, this task will create that profile.
- **Change the current color to enable better visibility of the entities**
- 1. Select **Wireframe color** from the Status bar at the bottom of the screen.



5. You are first prompted to **Mirror: select entities to mirror**. First select the **All** button on the **General Selection** ribbon bar as shown below:

ⓑ≰⊾ ◊   ☷ -   □ - №	-	00	1	r k	0 🔍
---------------------	---	----	---	-----	-----

6. The **Select All** dialog box appears on the left of the screen. Check mark the **Entities** box and then check mark **Lines** hold the **Ctrl** key down and then select **Arcs**.

Select All	
All Entities	
Xform Result Xform Group	
Group Manager	
Entities	
Color	
Width	
Style	
Point     Miscellaneous	
Points	
Arcs	
Curves on Surfaces	
Drafting     Solids	
Polygonal Meshes	
7. Click on the OK ic	on vert to complete this feature.
8. To move onto the	next step you now need to pick the End Selection icon
9. After selecting End	a Selection the <b>Mirror window</b> appears. Set the following values as
shown below:	
Mirror	Use new attributes
Move Copy Join	Determines the level and color attributes of the transformed entities.
Axis	Select this checkbox to display the Lovel and Color fields where you
Y 0.0	specify these attributes for the new geometry
	speeny mese autobales for me new geometry.
	Creating the transformed entities on a different level and in a unique
A 45.0 ▼ ()	color can make them easier to identify.
• •••	
0	To create transformed entities using the attributes of the original
	entities, deselect this option.
Mirror note and label text	
Preview	
Regen Fit	
Attributes	
Use New Attributes	
12	

- 10. Click on the OK icon <u>to complete this feature</u>.
- 11. Click on the **Clear Colors** is at the top right hand corner of the screen.

# TASK 6: SAVE THE DRAWING

- 1. Select File.
- 2. Select Save as.
- 3. In the File name box, type Mill-Lesson-9.
- 4. Save to an appropriate location.
- 5. Select the **Save** button to save the file and complete this function.

# **Toolpath Creation**

# TASK 7: DEFINE THE ROUGH STOCK USING STOCK SETUP

- 1. Fit to screen 🔛
- 2. Select the **plus** in front of **Properties** to expand the Toolpaths Group Properties. **Alt-O** will **Show/hide** Operations Manager pane.



4. Change the parameters to match the **Stock Setup** screenshot below:

### **Z zero** is at the top of the part.



5. Select the **Tool Settings** tab and change the parameters to match the Tool Settings screenshot below. To change the Material type follow the instructions below:



- 6. To change the Material type to Aluminium 6061 pick the Select button at the bottom of the Tool Settings page.
- 7. At the **Material List** dialog box open the **Source** drop down list and select **Mill – library**.
- From the Default Materials list select ALUMINIUM inch -6061 and then select

9. Select the OK button again to complete this Stock Setup function.

Your part should look similar to the screen shot below. With **X0 Y0** at the middle left side and **Z** zero at the top of the part.



# TASK 8: SURFACE HIGH SPEED OPTI-AREA

In this task you will use a 0.5 diameter bull end mill with a 0.125 corner radius to rough out the pocket using Surface High Speed>OptiArea.

### Optimized toolpaths

The 3D surface high speed OptiCore, OptiArea, and OptiRest toolpaths support cutters capable of machining very large depths of cut. It uses an aggressive, fast, intelligent roughing algorithm based on Mastercam's 2D high speed dynamic milling motion.

A single Optimized toolpath can cut material in two directions, on stepdowns (-Z) and step ups (+Z). This highly efficient bi-directional cutting strategy removes the maximum amount of material with the minimum of stepdowns, significantly reducing cycle times.

- 1. From the menu bar select TOOLPATHS>Surface High Speed>OptiArea...
- 2. When prompted to Enter new NC name ensure Mill-LESSON-9 is entered and then select the OK button .
- 3. You are first prompted to **Select Drive surfaces**, select the **All** button on the **General Selection** ribbon bar as shown below:



- 4. The Select All dialog box appears on the screen.
- 5. Click on the OK icon to complete and exit this feature.
- 6. To move onto the next step you now need to pick the End Selection icon

x

7. Select the **Containment boundary** button from the **Toolpath/surface selection** dialog box.

Use this dialog box to select all the geometry needed for a surface toolpath.

Each surface toolpath requires drive geometry selected from the graphics window or from a CAD file.



Toolpath/surface selection

8. On the screen you will now see the **Chaining dialog box** with **Chain set** and in the graphics screen a prompt to **Chain 2D tool containment boundary #1**. Ensure the **C-plane** radio button is activated. Now select the line as shown below:



9. After the boundary has been successfully chained select the OK button 
10. Select the OK button 
to exit the Toolpath/surface selection dialog box.

11. On the **Toolpath Type**, ensure the **Roughing** radio button and the **OptiArea** toolpath are selected.

	Roughing     Finishing     Core Roughing     Area     Clearance     Rest Roughing     OptiArea     OptiCore     OptiRest	Drive (11) (11) (11) (11) (11) (11) (11) (11
Axis Control 🔹		Containment boundary
۲		(1) 🗟 🐼

- 12. Now click on **Tool** and in the lower left corner of the **Toolpath parameters** page select the **Select library tool...** button. **Disable Filter active.**
- 13. Use the slider bar on the right of this dialog box to scroll down and locate a 0.5 diameter bull end mill with a 0.125 corner radius. Select the end mill by picking anywhere along its row.
- 14. Select the OK button to complete the selection of this tool.
- 15. Make changes to the **Tool parameters** page as shown below.



16. Select the **Cut parameters** page and make changes to this page as shown below: **Stock to leave on walls and floors** is set to **0.020**.

Toolpath Type Tool Holder Cut Parameters Tool containment Transitions Steep / Shallow Cut nking Parameters	Cutting method Climb Stepover 10.0 2 0.05 Stepdown 50.0 2 0.25 Stepup 10.0 2 0.05 Min toolpath radius 5.0 2 0.025	
Arc Filter / Tolerance Planes (WCS) Coolant Canned Text Misc Values Axis Control	Mill vertical walls       Gap size       Distance     7.87       % of tool diameter     1574.0	
Tool     1/2 BULL EN       Tool Diameter     0.5       Corner Radius     0.125       Feed Rate     12       Spindle Speed     2500       Coolant     On       Tool Length     3       Length Offset     1       Diameter Off     1	Motion < Gap size, micro.lift Micro lift distance Back feedrate Motion > Gap size, retract Never	Optimize cut order Tip comp Stock to leave on walls Stock to leave on floors 0.02

### **Cut Parameters - Optimized Toolpaths**

As stepdowns are calculated, the dynamic roughing motion clears the material in the -Z direction, avoiding any islands.

If you activate step up cuts in the toolpath's Cut Parameters, Mastercam calculates additional slices in the +Z direction to remove any material left behind between the step downs—for example, islands or large scallops on angled walls.

The step up cuts use a 2D high speed dynamic rest motion to clear leftover material. Step up cuts are ordered between stepdowns.

### Optimize cut order

Defines the cut order Mastercam applies to different cutting passes in the toolpath.

By Depth: Mastercam machines all cut passes z-level by z-level.

Next closest: Mastercam moves to the closest cut from where it finished the previous cut.

**By pocket:** Mastercam first machines all the stepdowns, moving from pocket to pocket. After all stepdowns on a z-level are machined to completion, Mastercam machines the step-ups by next closest, in the safest cut order.



17. Select the **Tool containment** page and make changes to this page as shown below.



18. Select the Transitions page and make changes to this page as shown below.



### 19. Select the **Steep / Shallow** page and ensure nothing is activated here.

### Linking Parameters

Use this page to create the links between the cutting passes. In general, you can think of linking moves as air moves when the tool is not in contact with the part, compared to cutting moves which are configured on the toolpath's Cut parameters page.

First, select a retract method. This determines how the tool will move between the end of one pass and the beginning of another. Then, use the Leads fields to control how the tool moves onto and off of the part at the start and end of each cutting pass. These moves are applied to each pass no matter which cutting pass is selected.

Finally, select a **Fitting option** to control how the entry and exit arcs will be fit into each pass.



21. Select the Arc Filter / Tolerance page and make changes to this page as shown below.

### Arc Filter/Tolerance

Use this page to control toolpath tolerances. Typically, this involves several sets of variables. Mastercam uses the values you enter here to convert the toolpath—originally created using G1, G2, G3 motions—to a refined set of "smoothed" G1 motions wherever possible, and within the tolerances you specify.

### **Tolerances Distribution**

The Tolerances Distribution fields display the total tolerance and the formula used to derive it. Adjust the total tolerance by entering a value in the Total tolerance field or by changing the values of the Cut, Line/Arc and/or Smoothing tolerances.

### Line/Arc Filtering and Smoothing

Toolpath filtering lets you replace multiple very small linear moves — within the filter tolerance — with single arc moves to simplify the toolpath. Smoothing distributes a toolpath's node points, avoiding the clustering and grouping of points that can cause marks and other imperfections.

Use the different checkboxes to enable or restrict arc creation in specific planes.

Enter minimum and maximum arc radius values to control the size of the arcs Mastercam creates in the filtered toolpath.

Define the smoothing tolerance by shifting, removing and/or adding node points along your toolpath.

22. Turn the Coolant Flood on.

23. Select the OK button **v** to complete this toolpath.

24. It may take a while for Mastercam to create the toolpath. Mastercam's multi-threading functionality will calculate the toolpath while you continue to work. The green spool of thread indicates threading is active.



25. If threading is not active, you can turn it on by selecting **Settings>Configuration...** then making the selection indicated below on the **Toolpaths** tab.



# TASK 9:

## FINISH THE POCKET USING SURFACE HIGH SPEED HYBRID

- In this task you will use a 0.5 diameter Ball end mill to finish the pocket.
- Mastercam's Hybrid finishing toolpath addresses steep and shallow areas utilizing both scallop and constant Z approaches in a single toolpath.
- The toolpath switches seamlessly between both methods and cuts in a logical optimized order.
- Most of the parameters you define for the toolpath are similar or the same as other surface high speed finishing toolpaths. However, the Step group of settings on the Cut Parameters page are unique. Use them to control how Mastercam defines steep and shallow areas.
- 1. From the menu bar select TOOLPATHS>Surface High Speed>Hybrid...
- 2. You are first prompted to **Select Drive surfaces**, select the **All** button on the **General Selection** ribbon bar as shown below:



- 3. The Select All dialog box appears on the screen.
- 4. Click on the OK icon is to complete and exit this feature.
- 5. To move onto the next step you now need to pick the End Selection icon
- 6. Select the Containment boundary button from the Toolpath/surface selection dialog box.



7. On the screen you will now see the Chaining dialog box with Chain set and in the graphics screen a prompt to Chain 2D tool containment boundary #1. Ensure the C-plane radio button is activated. Toolpath display has been turned off for clarity ALT + T. Now select the line as shown below:



- 8. After the boundary has been successfully chained select the OK button
- 9. Select the OK button is to exit the **Toolpath/surface selection** dialog box.
- 10. On the **Toolpath Type**, ensure the **Finishing** radio button and the **Hybrid** toolpath are selected.



- 11. Select the **Tool** selection page, then **Select library tool...** button.
- 12. Select the **Filter** button on the right side of the **Tool selection** dialog box.
- 13. Select the **None** button in the Tool Types section.
- 14. Click on the Endmill2 Sphere type icon as shown in the picture (1) below:
- 15. Select the drop down arrow in the Tool diameter (2) field and set it to Equal.
- 16. Input the tool diameter (3) as **0.5**.

![](_page_27_Picture_7.jpeg)

19. Select the OK button voice to complete the selection of this tool.

Toolpath Type Tool dia: 0.5 Tool Holder Dia. Cor. rad. # Tool Name Corner radius: 0.25 1/2 BULL ENDMILL 0.125 RAD 0.5 0.125 1 Cut Parameters 172 BALL ENDMILL Tool name: 1/2 BALL ENDMILL Transitions Steep / Shallow Tool #: 2 Len. offset: 2 Linking Parameters ÷ Head # 0 Dia. offset: 2 Arc Filter / Tolerance É٩. Planes (WCS) Coolant Canned Text Misc Values - Axis Control Spindle direction: CW • Axis Combination Rotary Axis Control Feed rate: 15.0 Spindle speed: 2500 ٠ Ш Þ SFM 327.2251 Quick View Settings FPT: 0.0015 Right-click for options Tool 1/2 BALL EN. 🔺 Retract rate: 50.0 Plunge rate: 15.0 Tool Diameter 0.5 Filter Active Filter.. Select library tool... E Force tool change 📝 Rapid Retract Corner Radius 0.25 Feed Rate 15 Tool inspection / change Comment Spindle Speed 2500 400.0 Inches Coolant On Tool Length 40.0 3 Minutes Length Offset 2 Diameter Off... 2 To batch ۰ III

20. Make changes to the Tool page as shown below:

Toolpath Type 🗸 Tool Closed contours Climb • Holder Open contours One Way • Step ė... 🗸 Cut Parameters Transitions 0.01 Z stepdown Steep / Shallow Linking Parameters 45.0 Limiting angle Arc Filter / Tolerance 0.02 3D stepover Planes (WCS) Coolant Canned Text Misc Values 3D passes Keep tool down within - Axis Control 7.87 🔘 Distance Axis Combination V Preserve Z passes Rotary Axis Control % of tool diameter 20.0 Closed offsets Offset method Quick View Settings 🔽 Optimize cut order 1/2 BALL EN. 🔺 Tool Tic Tool containment Tool Diameter 0.5 Tip comp Compensate to: Corner Radius 0.25 Feed Rate 15 Ξ Inside Outside Stock to leave 0.0 Spindle Speed 2500 on walls Offset ( **Dff** Coolant. Stock to leave n n Add offset distance to tool radius Tool Length 3 on floors Length Offset 2 Stock to leave Total offset distance = 0 0.0 Diameter Off... 2 on check < III.

21. Select the **Cut Parameters** page and make changes to this page as shown below.

### **Cut Parameters**

Use this page to configure the cutting passes for a hybrid toolpath. This is a finishing toolpath which generates waterline-style cut passes for steep regions and scallop cut passes for shallow regions. Mastercam switches smoothly between both styles to cut in a logical optimized order. **Z stepdown** 

Defines the constant Z distance between adjacent stepdowns. Mastercam uses these stepdowns in combination with the Limiting Angle and 3D stepover to calculate cut passes for the hybrid toolpath.

Mastercam first slices the entire model into sections defined by the Z Stepdown distance. It then analyzes the drive surface's slope transition between each stepdown along the specified **Limiting Angle.** 

If the drive surface's slope transition within the stepdown distance is less than the applied limiting angle, the hybrid toolpath considers it steep and a single 2D waterline cutting pass is generated. Otherwise, the stepdown is defined as shallow. Mastercam uses the 3D stepover value to create 3D scallop cut passes along the shallow slope.

### 3D stepover

Defines the spacing between 3D scallop-style cutting passes in shallow stepdowns.

### Preserve Z passes

Select to maintain Z passes in steep areas. Passes in shallow areas are calculated based on the Offset method. Deselect to calculate collapse motion across the entire part when a shallow region is encountered.

### Offset method

Select a method for handling the boundaries between steep and shallow areas from the dropdown.

**Closed offsets:** The boundaries are treated as closed chains when calculating the 3D collapse motion.

Toolpath Type					
√ I ool Holder					
Holder					
Durid Cut Parameters					
Steep / Challers	-				
Linking Parameters	Iransition				
Arc Filter / Tolerance	Tangential ramp	🔘 Ramp	© S	traight	
Planes (WCS)		10.0			
Coolant		Angle 10.0			
Canned Text					
Misc Values					
Axis Control	(				
Axis Combination		/			
Rotary Axis Control	<b>(</b> 5	×			
uiek Mieru Cettinge		<del>_</del>			
uick view settings					
Tool 1/2 BALL EN.					
Tool Diameter 0.5					
Corner Radius 0.25					
eed Rate 15					
Spindle Speed 2500					
Loolant Un	- Out	tput 3D arc moves	Skip pockets	0.55	
Lool Length 3			smaller than		
Length Uffset 2					
Diameter Urr 2					
ransition Page - Hy se this page to conf vels. These moves oolpath.	<b>vbrid</b> igure the entry moves t control the transition to	that the tool will ma a new set of cuts	ake as it trans on a different	itions to ne Z level.	w Z
ransition Page - Hy se this page to conf evels. These moves polpath. elect <b>Tangential ra</b> lastercam inserts ar nd out of the move.	<b>/brid</b> igure the entry moves t control the transition to <b>mp</b> to create a true high cs at the beginning and	that the tool will may a new set of cuts h speed transition d end of the ramp fo	ake as it trans on a different between the or the smooth	itions to ne Z level. cutting pass nest tool mo	w Z ses. tion into
ransition Page - Hy se this page to confivels. These moves oolpath. elect <b>Tangential ra</b> lastercam inserts ar nd out of the move. 3. Select the <b>Steep</b>	vbrid igure the entry moves t control the transition to mp to create a true high cs at the beginning and Shallow page and en	that the tool will may a new set of cuts h speed transition d end of the ramp for sure nothing is act	ake as it trans on a different between the or the smooth ivated here.	itions to ne Z level. cutting pass nest tool mo	w Z ses. tion into
ransition Page - Hy se this page to confivels. These moves olpath. elect <b>Tangential ra</b> astercam inserts ar nd out of the move. 3. Select the <b>Steep</b>	vbrid igure the entry moves t control the transition to mp to create a true high cs at the beginning and Shallow page and en	that the tool will mat a new set of cuts h speed transition d end of the ramp for usure nothing is act	ake as it trans on a different between the or the smooth	sitions to ne Z level. cutting pass nest tool mo	w Z ses. tion into
ransition Page - Hy se this page to confivels. These moves olpath. elect <b>Tangential ra</b> astercam inserts ar nd out of the move. 3. Select the <b>Steep</b>	vbrid igure the entry moves t control the transition to mp to create a true high cs at the beginning and Shallow page and en	that the tool will may a new set of cuts h speed transition d end of the ramp for usure nothing is act	ake as it trans on a different between the or the smooth	itions to ne Z level. cutting pass nest tool mo	w Z ses. tion into
ransition Page - Hy se this page to confivels. These moves polpath. elect <b>Tangential ra</b> lastercam inserts ar nd out of the move. 3. Select the <b>Steep</b>	vbrid igure the entry moves t control the transition to mp to create a true high cs at the beginning and Shallow page and en	that the tool will may a new set of cuts h speed transition d end of the ramp for sure nothing is act	ake as it trans on a different between the or the smooth ivated here.	itions to ne Z level. cutting pass nest tool mo	w Z ses. tion into
ransition Page - Hy se this page to conf vels. These moves oolpath. elect <b>Tangential ra</b> lastercam inserts ar nd out of the move. 3. Select the <b>Steep</b> Toolpath Type Tool Holder	vbrid igure the entry moves t control the transition to mp to create a true high cs at the beginning and Shallow page and en	that the tool will may a new set of cuts h speed transition d end of the ramp for sure nothing is act	ake as it trans on a different between the or the smooth	itions to ne Z level. cutting pass nest tool mo	w Z ses. tion into
ransition Page - Hy se this page to conf evels. These moves oolpath. elect <b>Tangential ra</b> lastercam inserts ar nd out of the move. 3. Select the <b>Steep</b> Toolpath Type Tool Holder	vbrid igure the entry moves t control the transition to mp to create a true high cs at the beginning and Shallow page and en	that the tool will may a new set of cuts h speed transition d end of the ramp for sure nothing is act	ake as it trans on a different between the or the smooth	itions to ne Z level. cutting pass nest tool mo	w Z ses. tion into
ransition Page - Hy se this page to confivels. These moves oolpath. elect <b>Tangential ra</b> lastercam inserts ar nd out of the move. 3. Select the Steep Toolpath Type Tool Holder	vbrid igure the entry moves t control the transition to mp to create a true high cs at the beginning and Shallow page and en	that the tool will may a new set of cuts h speed transition d end of the ramp for sure nothing is act	ake as it trans on a different between the or the smooth	sitions to ne Z level. cutting pass nest tool mo	w Z ses. tion into
ransition Page - Hy se this page to confivels. These moves oolpath. elect <b>Tangential ra</b> lastercam inserts ar nd out of the move. 3. Select the Steep Toolpath Type Tool Holder Cut Parameters Tool containment Transitions	vbrid igure the entry moves t control the transition to mp to create a true high cs at the beginning and Shallow page and en	that the tool will mat a new set of cuts h speed transition d end of the ramp for sure nothing is act	ake as it trans on a different between the or the smooth	sitions to ne Z level. cutting pass nest tool mo	w Z ses. tion into
ransition Page - Hy se this page to conf vels. These moves olpath. elect <b>Tangential ra</b> astercam inserts ar nd out of the move. 3. Select the <b>Steep</b> Toolpath Type Vol Cut Parameters Cut Parameters Cut Parameters Steep / Shellow	vbrid igure the entry moves to control the transition to mp to create a true high cs at the beginning and V Shallow page and en	that the tool will mat a new set of cuts h speed transition d end of the ramp for sure nothing is act	ake as it trans on a different between the or the smooth	sitions to ne Z level. cutting pass nest tool mo	w Z ses. tion into
ransition Page - Hy se this page to confivels. These moves oolpath. elect <b>Tangential ra</b> lastercam inserts ar nd out of the move. 3. Select the Steep Toolpath Type Tool Holder Cut Parameters Cut Parameters Cut Parameters Steep / Shallow Cut Parameters	vbrid igure the entry moves to control the transition to mp to create a true high cs at the beginning and V Shallow page and en	that the tool will mat a new set of cuts h speed transition d end of the ramp for sure nothing is act	ake as it trans on a different between the or the smooth	sitions to ne Z level. cutting pass nest tool mo	w Z ses. tion into
ransition Page - Hy se this page to conf evels. These moves polpath. elect <b>Tangential ra</b> lastercam inserts ar nd out of the move. 3. Select the Steep Toolpath Type Cut Parameters Cut Parameters Cut Parameters Cut Parameters Cut Parameters Cut Parameters Cut Parameters Cut Parameters Cut Parameters Cut Parameters	vbrid igure the entry moves to control the transition to mp to create a true high cs at the beginning and V Shallow page and en	that the tool will math a new set of cuts h speed transition d end of the ramp for sure nothing is act	ake as it trans on a different between the or the smooth	sitions to ne Z level. cutting pass nest tool mo	w Z ses. tion into
ransition Page - Hy se this page to conf evels. These moves polpath. elect <b>Tangential ra</b> lastercam inserts ar nd out of the move. 3. Select the Steep Toolpath Type Tool Holder Cut Parameters Cut Parameters	vbrid igure the entry moves to control the transition to mp to create a true high cs at the beginning and v Shallow page and en	that the tool will match a new set of cuts h speed transition d end of the ramp for sure nothing is act	ake as it trans on a different between the or the smooth	sitions to ne Z level. cutting pass nest tool mo	w Z ses. tion into
ransition Page - Hy se this page to conf evels. These moves polpath. elect <b>Tangential ra</b> lastercam inserts ar nd out of the move. <b>3. Select the Steep</b> <b>3. Select the Steep</b> <b>4.</b> Toolpath Type <b>5.</b> Tool containment Transitions <b>5.</b> Steep / Shellow <b>6.</b> Linking Parameters <b>6.</b> Arc Filter / Tolerance Planes (WCS)	vbrid igure the entry moves to control the transition to mp to create a true high cs at the beginning and v Shallow page and en	that the tool will math a new set of cuts h speed transition d end of the ramp for sure nothing is act	ake as it trans on a different between the or the smooth ivated here.	sitions to ne Z level. cutting pass nest tool mo	w Z ses. tion into
ransition Page - Hy se this page to conf evels. These moves polpath. elect <b>Tangential ra</b> lastercam inserts ar nd out of the move. <b>3. Select the Steep</b> <b>3. Select the Steep</b> <b>4.</b> Toolpath Type <b>5.</b> Tool containment Transitions <b>5.</b> Steep / Shallow <b>6.</b> Linking Parameters <b>6.</b> Arc Filter / Tolerance Planes (WCS) Coolant	vbrid igure the entry moves to control the transition to mp to create a true high cs at the beginning and V Shallow page and en	that the tool will mathematical anew set of cuts h speed transition d end of the ramp for sure nothing is act	ake as it trans on a different between the or the smooth ivated here.	sitions to ne Z level. cutting pass nest tool mo	w Z ses. tion into
ransition Page - Hy         se this page to conference         se this page to conference         evels. These moves         solpath.         elect Tangential range         lastercam inserts ar         ad out of the move.         3. Select the Steep         Toolpath Type         Tool         Holder         Cut Parameters         Steep / Shellow         Enrors         Arc Filter / Tolerance         Planes (WCS)         Coolant         Canned Text	vbrid igure the entry moves to control the transition to mp to create a true high cs at the beginning and V Shallow page and en	that the tool will mathematical anew set of cuts of the speed transition d end of the ramp for the ramp for the sure nothing is act sure nothing is act of the sure nothing is act of t	ake as it trans on a different between the or the smooth ivated here.	sitions to ne Z level. cutting pass nest tool mo	w Z ses. tion into
ransition Page - Hy         se this page to conference         se this page to conference         elect Tangential ra         lastercam inserts ar         ad out of the move.         3. Select the Steep         Toolpath Type         Yool         Holder         Yool containment         Transitions         Steep / Shallow         Arc Filter / Tolerance         Planes (WCS)         Coolant         Canned Text         Misc Values	vorid igure the entry moves to control the transition to mp to create a true high cs at the beginning and V Shallow page and en Z depth- Use Z	that the tool will mathematical anew set of cuts of the speed transition d end of the ramp for a sure nothing is act sure nothing is act depths Detect limits	ake as it trans on a different between the or the smooth	sitions to ne Z level. cutting pass nest tool mo	w Z ses. tion into
ransition Page - Hy         se this page to conference         se this page to conference         elect Tangential range         lastercam inserts ar         ad out of the move.         3. Select the Steep         Toolpath Type         Yool         Holder         Yool containment         Transitions         Steep 7 Shallow         Arc Filter / Tolerance         Planes (WCS)         Coolant         Canned Text         Misc Values         Axis Control	vorid igure the entry moves to control the transition to mp to create a true high cs at the beginning and V Shallow page and en C depth Use 2 Min	that the tool will mathematical anew set of cuts of the speed transition d end of the ramp for a sure nothing is act sure nothing is act sure between the sure	ake as it trans on a different between the or the smooth ivated here.	sitions to ne	w Z ses. tion into
ransition Page - Hy se this page to confivels. These moves olpath. elect <b>Tangential ra</b> astercam inserts ar nd out of the move. <b>3. Select the Steep</b> <b>3. Select the Steep</b> <b>4. Select the Steep</b> <b>5. Cut Parameters</b> <b>5. Cut Parameters</b> <b>5. Cut Parameters</b> <b>5. Cut Parameters</b> <b>5. Select 7 Shallow</b> <b>6. Linking Parameters</b> <b>6. Arc Filter / Tolerance</b> <b>9. Planes (WCS)</b> <b>Coolant</b> <b>Canned Text</b> <b>Misc Values</b> <b>Axis Control</b>	vbrid igure the entry moves to control the transition to mp to create a true high cs at the beginning and v Shallow page and en v C depth Use Z Min	that the tool will may a new set of cuts h speed transition d end of the ramp for sure nothing is act sure nothing is act depths Detect limits imum depth 0.0	ake as it trans on a different between the or the smooth ivated here.	sitions to ne Z level. cutting pass nest tool mo	w Z ses. tion into
ransition Page - Hy se this page to confivels. These moves olpath. elect <b>Tangential ra</b> astercam inserts ar nd out of the move. <b>3. Select the Steep</b> Toolpath Type Tool Holder Cut Parameters Cut Parameters	vbrid igure the entry moves to control the transition to mp to create a true high cs at the beginning and <b>Shallow</b> page and en <b>Shallow</b> page and en <b>C</b> Use Z Mini Mas	that the tool will may a new set of cuts h speed transition d end of the ramp for sure nothing is act sure nothing is act depths Detect limits imum depth 0.0	ake as it trans on a different between the or the smooth ivated here.	sitions to ne Z level. cutting pass nest tool mo	w Z ses. tion into

22. Select the **Transitions** page and make changes to this page as shown below.

Quick View Settings

Toolpath Type Retracts Tool 3 1.0 Clearance plane Full Vertical Retract Holder Absolute 🔘 Incremental 500.0 Output feed move Eut Parameters 0.15 Curl up Transitions Steep / Shallow 0.15 Linking Parameters <u>ن</u>… 🗸 0.15 Part clearance Arc Filter / Tolerance Planes (WCS) Coolant Canned Text Misc Values Axis Control Axis Combination ads Linear entry/exit (incremental) Rotary Axis Control 0.025 Fitting Minimize Trimming Quick View Settings 0.075 Vertical arc entry 1/2 BALL EN. 🔺 Tool Max trimming 0.05 Vertical arc exit 0.075 distance Tool Diameter 0.5 Corner Radius 0.25 0.075 Horizontal arc entry Feed Rate 15 Spindle Speed 2500 0.075 Horizontal arc exit Coolant On 10.0 Tool Length 3 Max ramp angle Length Offset 2 Ramp height **P**(1) Diameter Off... 2 < III.

### 24. Select the Linking Parameters page and make changes to this page as shown below.

### **Linking Parameters**

Use this page to create the **links between the cutting passes**. In general, you can think of linking moves as air moves when the tool is not in contact with the part, compared to cutting moves which are configured on the toolpath's Cut parameters page.

Holder	Total tolerance	e: 0.001
En V Cut Parameters		
Transitions	Cut	Line Man
Steep / Shallow	tolerance	tolerance tolerance
Linking Parameters	0.00033 + 0	0.00033 + 0.00034
Planes W/CS)		33.0 % 🔲 34.0 🔪 %
Coolant		$\sim$
Canned Text	I line /Are Eilbering California	Caracthing Cattings
Misc Values	Line/Aid Filtering Settings	Shibothing settings
Axis Control	Create arcs in:	Use Fixed Segment Length
Rotary Axis Control	🔍 XY (G17) 🔍 XZ (G18) 🔍 YZ (G19)	Segment Length
	🔲 One way filtering	Segment Length 0.02
uick View Settings	Minimum arc radius	Shift points randomly along toolpath
Tool 1/2 BALL EN. 🔺		
Tool Diameter 0.5	Maximum arc radius 100.0	Minimize number of points
Corner Madius 0.25 Feed Bate 15	Use maximal tolerance value for both	Present arcs as line segments
Spindle Speed 2500	Tighten Line filtering tolerance	These in arcs as the segments
Coolant On		
Tool Length 3	<ul> <li>Lighten Arc tiltering tolerance</li> </ul>	
Length Offset 2	0.000017 5.0%	
rc Filter/Tolerance se this page to con	e trol toolpath tolerances. Typically, this	involves several sets of variables.
arc Filter/Tolerance lse this page to con lastercam uses the 62, G3 motions—to olerances you speci	e trol toolpath tolerances. Typically, this values you enter here to convert the to a refined set of "smoothed" G1 motion fy.	involves several sets of variables. oolpath—originally created using G1, as wherever possible, and within the
<b>Inc Filter/Tolerance</b> lese this page to con lastercam uses the 2, G3 motions—to olerances you speci define the smoothing	trol toolpath tolerances. Typically, this values you enter here to convert the to a refined set of "smoothed" G1 motion fy.	involves several sets of variables. oolpath—originally created using G1, is wherever possible, and within the or adding node points along your
<b>rc Filter/Tolerance</b> se this page to con lastercam uses the 2, G3 motions—to plerances you speci pefine the smoothing polpath.	trol toolpath tolerances. Typically, this values you enter here to convert the to a refined set of "smoothed" G1 motion fy. g tolerance by shifting, removing and/c	involves several sets of variables. oolpath—originally created using G1, as wherever possible, and within the or adding node points along your
rc Filter/Tolerance se this page to con lastercam uses the 2, G3 motions—to plerances you speci efine the smoothing polpath.	trol toolpath tolerances. Typically, this values you enter here to convert the to a refined set of "smoothed" G1 motion fy. g tolerance by shifting, removing and/c	involves several sets of variables. oolpath—originally created using G1, as wherever possible, and within the or adding node points along your
rc Filter/Tolerance se this page to con lastercam uses the 2, G3 motions—to plerances you speci efine the smoothing polpath.	trol toolpath tolerances. Typically, this values you enter here to convert the to a refined set of "smoothed" G1 motion fy. g tolerance by shifting, removing and/c	involves several sets of variables. oolpath—originally created using G1, as wherever possible, and within the or adding node points along your
rc Filter/Tolerance se this page to con lastercam uses the 2, G3 motions—to plerances you speci- efine the smoothing polpath. 6. Turn the Coolan	trol toolpath tolerances. Typically, this values you enter here to convert the to a refined set of "smoothed" G1 motion fy. g tolerance by shifting, removing and/c	involves several sets of variables. oolpath—originally created using G1, as wherever possible, and within the or adding node points along your
rc Filter/Tolerance se this page to con lastercam uses the 2, G3 motions—to plerances you speci- efine the smoothing polpath. 6. Turn the Coolam 7. Select the OK bu	trol toolpath tolerances. Typically, this values you enter here to convert the to a refined set of "smoothed" G1 motion fy. g tolerance by shifting, removing and/c t Flood on. tton to complete this toolpath.	involves several sets of variables. oolpath—originally created using G1, as wherever possible, and within the or adding node points along your
arc Filter/Tolerance se this page to con lastercam uses the i2, G3 motions—to blerances you speci- refine the smoothing oolpath. 6. Turn the <b>Coolam</b> 7. Select the OK bu	trol toolpath tolerances. Typically, this values you enter here to convert the to a refined set of "smoothed" G1 motion fy. g tolerance by shifting, removing and/c t Flood on. tton is to complete this toolpath.	involves several sets of variables. oolpath—originally created using G1, as wherever possible, and within the or adding node points along your
<b>arc Filter/Tolerance</b> lese this page to con lastercam uses the 22, G3 motions—to blerances you speci- befine the smoothing bolpath. 6. Turn the <b>Coolam</b> 7. Select the OK bu	trol toolpath tolerances. Typically, this values you enter here to convert the to a refined set of "smoothed" G1 motion fy. g tolerance by shifting, removing and/c t Flood on. tton to complete this toolpath.	involves several sets of variables. oolpath—originally created using G1, as wherever possible, and within the or adding node points along your
<b>arc Filter/Tolerance</b> lese this page to con- lastercam uses the 52, G3 motions—to olerances you speci- befine the smoothing oolpath. 6. Turn the <b>Coolan</b> 7. Select the OK bu	trol toolpath tolerances. Typically, this values you enter here to convert the to a refined set of "smoothed" G1 motion fy.	involves several sets of variables. oolpath—originally created using G1, as wherever possible, and within the or adding node points along your
<b>arc Filter/Tolerance</b> lese this page to con lastercam uses the 22, G3 motions—to olerances you speci- befine the smoothing oolpath. 6. Turn the <b>Coolan</b> 7. Select the OK bu	trol toolpath tolerances. Typically, this values you enter here to convert the to a refined set of "smoothed" G1 motion fy. g tolerance by shifting, removing and/c t Flood on. tton to complete this toolpath.	involves several sets of variables. oolpath—originally created using G1, as wherever possible, and within the or adding node points along your
<b>Arc Filter/Tolerance</b> lese this page to con- lastercam uses the 52, G3 motions—to olerances you speci- befine the smoothing colpath. 6. Turn the <b>Coolan</b> 7. Select the OK bu	trol toolpath tolerances. Typically, this values you enter here to convert the to a refined set of "smoothed" G1 motion fy. to tolerance by shifting, removing and/c to complete this toolpath.	involves several sets of variables. oolpath—originally created using G1, as wherever possible, and within the or adding node points along your
Arc Filter/Tolerance lese this page to con lastercam uses the 32, G3 motions—to olerances you speci- befine the smoothing polpath. 6. Turn the <b>Coolan</b> 7. Select the OK bu	trol toolpath tolerances. Typically, this values you enter here to convert the to a refined set of "smoothed" G1 motion fy. g tolerance by shifting, removing and/o t Flood on. tton is to complete this toolpath.	involves several sets of variables. oolpath—originally created using G1, as wherever possible, and within the or adding node points along your
Arc Filter/Tolerance lese this page to con lastercam uses the i2, G3 motions—to olerances you speci pefine the smoothing polpath. 6. Turn the <b>Coolam</b> 7. Select the OK bu	trol toolpath tolerances. Typically, this values you enter here to convert the to a refined set of "smoothed" G1 motion fy. g tolerance by shifting, removing and/c t Flood on. tton is to complete this toolpath.	involves several sets of variables. oolpath—originally created using G1, as wherever possible, and within the or adding node points along your
Arc Filter/Tolerance lese this page to con lastercam uses the 62, G3 motions—to olerances you speci oefine the smoothing oolpath. 6. Turn the <b>Coolan</b> 7. Select the OK bu	trol toolpath tolerances. Typically, this values you enter here to convert the to a refined set of "smoothed" G1 motion fy. g tolerance by shifting, removing and/c t Flood on. tton to complete this toolpath.	involves several sets of variables. oolpath—originally created using G1, as wherever possible, and within the or adding node points along your
Arc Filter/Tolerance Use this page to con Mastercam uses the 32, G3 motions—to olerances you speci pefine the smoothing polpath. 6. Turn the <b>Coolan</b> 7. Select the OK bu	trol toolpath tolerances. Typically, this values you enter here to convert the to a refined set of "smoothed" G1 motion fy. to tolerance by shifting, removing and/o to complete this toolpath.	involves several sets of variables. oolpath—originally created using G1, as wherever possible, and within the or adding node points along your
Arc Filter/Tolerance lese this page to con lastercam uses the 2, G3 motions—to blerances you speci befine the smoothing bolpath. 6. Turn the <b>Coolan</b> 7. Select the OK bu	trol toolpath tolerances. Typically, this values you enter here to convert the to a refined set of "smoothed" G1 motion fy. g tolerance by shifting, removing and/c	involves several sets of variables. oolpath—originally created using G1, as wherever possible, and within the or adding node points along your

25. Select the Arc Filter / Tolerance page and make changes to this page as shown below.

28. It may take a while for Mastercam to create the toolpath. Mastercam's multi-threading functionality will calculate the toolpath while you continue to work. The green spool of thread indicates threading is active.

![](_page_33_Figure_2.jpeg)

The screen should look like the image below with the toolpaths displayed:

![](_page_33_Figure_4.jpeg)

# TASK 10: VERIFY THE TOOLPATH

1. Set the graphics view to the Isometric View by using the toolbar icon at the top of the

screen.

- 2. Select the Screen Fit icon found at the top of the screen to fit the part to the screen.
- 3. In the **Toolpaths Manager** pick all the operations to verify by picking the **Select All** icon
- 4. Select the Verify selected operations icon shown below:

![](_page_34_Figure_7.jpeg)

5. Maximize the Backplot/Verify window if required.

View

6. Activate the Follow option in the Toolpath section of the Verify tab.

/erify

![](_page_34_Picture_10.jpeg)

7. Now select the Home Tab.

Home

File

8. Activate the options shown below in the **Visibility** section of the **Home** tab. **Initial Stock not** activated.

![](_page_34_Figure_13.jpeg)

9. Activate the Color Loop.

![](_page_34_Picture_15.jpeg)

File	Hom	e Viev	w 🗡 Ve	rify					
Collision Report	GD G10 G08 Move List	Fit I	Isometric	Top ○ Top Right ○ Front ▼	Single View	2 Views in Rows	2 Views in Columns	4 Views	Restore default view
Sho	w		3D Vie	ew			Viewport	s	

10. At the top of the screen select the View tab, the Isometric icon and then select Fit.

11. In the lower right corner of the screen now set the run **Speed** to slow by moving the slider bar pointer over to the left as shown below.

![](_page_35_Figure_4.jpeg)

12. Now select the Play Simulation button to review the toolpaths.

![](_page_35_Figure_6.jpeg)

13. Select the **Close** button in the top right hand corner to exit Verify.

# TASK 11: SAVE THE UPDATED MASTERCAM FILE

1. Select the save icon from the toolbar.

# TASK 12: POST AND CREATE THE CNC CODE FILE

### **Please Note:**

Users of the Mastercam **Home Learning Edition** (HLE) will not be able to Post and Create the CNC code file.

- 1. Ensure all the operations are selected by picking the **Select All** icon from the Toolpaths manager.
- 2. Select the Post selected operations icon G1 from the Toolpaths manager.

![](_page_36_Picture_8.jpeg)

3. In the **Post processing** window, make the necessary changes as shown below:

![](_page_36_Picture_10.jpeg)

5. Ensure the same name as your Mastercam part file name is displayed in the File name window as shown below:

File name:	MILL-LESSON-9	]
Save as type:	NC Files (*.NC)	]

- 6. Select the **Save** button.
- 7. The CNC code file opens up in the default editor:

MILL-LE	SSON-9.NC ×
7	(MATERIAL - ALUMINUM INCH - 6061)
8	(T1  1/2 BULL ENDMILL 0.125 RAD H1 D1 TOOL DIA5)
9	(T2  1/2 BALL ENDMILL H2 D2 TOOL DIA5)
10	N1 G20
11	N2 G0 G17 G40 G49 G80 G90
12	N3 T1 M6
13	N4 G0 G90 G54 X3.1367 Y.0614 A0. S2500 M3
14	N5 G43 H1 Z1.
15	N6 MB
16	N7 Z.2666
17	N8 G1 Z.2416 #12.
18	N9 X3.1423 X.0713 Z.2019
19	N10 X3.1575 Y.098 Z.1742
20	N11 X3.175 Y.1352 Z.164

8. Select the in the top right corner to exit the CNC editor.

This completes Mill-Lesson-9.

# MILL-LESSON-9 EXERCISES

![](_page_38_Figure_2.jpeg)

![](_page_39_Figure_1.jpeg)